



Installation instruction



1 Remove the screws and the metal plate.

4


Installation instruction



2 Take out the expand DC plug and put it as shown.

5


Installation instruction



3 Put the DC plug into another cradle.

6

Installation instruction



4 Install the screws as shown.


7

Support information

- 1 Do not charge in direct sunlight or humid environment. If the power adapter is faulty, please contact the manufacturer to replace it with a new one.
- 2 Do not incinerate or short-circuit the cradle, otherwise, danger may occur.
- 3 Do not throw, drop or strike the cradle. Doing so might damage the internal components and result in malfunction.
- 4 Only use the a soft cloth to clean the terminal. Cleaning it with wet cloth or benzene/thinner/ other volatile chemicals may deform and shorten the service life of the terminal's shell.
- 5 For safety, please use the original adapter during charging. Please try to avoid charging for a long time. After fully charged, please disconnect the power supply.

8


Installation instruction



LED in the cradle indicates the power status of the cradle. While the LED is red, it means the power of the cradle is on.

1

Installation instruction




Indication of charging LED on scanner

Green LED on	Fully charged
Red LED on	Charging in progress

2

Installation instruction



A maximum of 5 cradles can be combined.

3

Support information



For more information and technical support, please visit newland-id.com/contact

Newland Europe BV
Rolweg 25
4104 AV Culemborg
The Netherlands



SCD20
Charging Cradle for WD4



Quick Guide V1.0